

## Errors found in 2<sup>nd</sup> Revisions

### Icom IC M802 Made Simple for Cruisers

Page 53 – Error on 8 MHz frequency. Should be 8,291.0

<b>GMDSS Simplex Channels</b>	
2,182.0 kHz*	8,291.0 kHz
4,125.0 kHz	12,290.0 kHz
6,215.0 kHz	16,420.0 kHz

### Icom IC M802 Starting from Scratch

Page 123 – Error on 8 MHz frequency. Should be 8,291.0

<b>GMDSS Simplex Channels</b>	
2,182.0 kHz*	8,291.0 kHz
4,125.0 kHz	12,290.0 kHz
6,215.0 kHz	16,420.0 kHz